



Philips Firmware Upgrade Information

Upgrade for types: PBDVD824B/00 (Black) → Drive type number on label.
PBDVD824G/00 (Grey)

Upgrade for string: PBDVD824P → Drive name as seen in Windows TM

From firmware: B1.x

To new firmware: B1.5

Date: 12 August 2005

Table of contents:

1.	Version History	2
2.	Important Warning:	2



Philips does not and can not warrant the performance of/the results you may obtain using this software.
At no time, Philips can held liable for any damages including (but not limited to) lost profits or consequential damages or for any claim by any other party.

1. Version History

First version is B1.0

Form firmware B1.0 to B1.2 (B1.1 does not exist)

- Improved writing quality on some DVD+R media.

Changes from firmware B1.2 to B1.3

- Improved recognition of copied DVD discs.
- Corrected write speed shown in CDSpeed.
- Improved reading of table of contents on DVD-R and DVD-RW.
- InCD can now format new DVD+RW discs.
- Improved writing quality on some DVD+R and DVD+RW media.

Changes from firmware B1.3 to B1.4

- Playing of recorded DVD+R Double Layer discs is added

Changes from firmware B1.4 to B1.5

- Released 12 August 2005.
- Improved writing quality on unknown DVD+R and DVD+RW media by using an improved algorithm.

2. Important Warning:

This upgrade is only valid if you are using a B1.x firmware.

When you have a PBDVD824P drive with firmware B2.x, you can not use this upgrade.
Choose the PBDVD824B/20 or PBDVD824G/20 model to find your latest upgrade.

When you have a PBDVD824DP drive with firmware B3.x, you can not use this upgrade.
Choose the PBDVD824B/30 or PBDVD824G/30 model to find your latest upgrade.

For more info, see the included document:
Upgrading Troubleshooting and Frequently Asked Questions.pdf